

GOYERIAMENT CERTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location					
Address 1380	RIVIERA AV	10. 5		Telephone Number	
City St. Croix	,		ZIP55043 Pro	pperty ID No./GEO Code	
Owner Karen	A . 1	Pumping Date	9/3/15		
Contractor					
Maintainer MEYE	RSEWER	MPCA License	No. 915	Telephone Number 657	-459-016
What was done to the system?			Report Liquid Capacity in Gallons		
Tank(s) Pumped	2		Tank 1: 1250	Pumped Tank 2: 123	
Sludge and scum measured.			Tank 3:	Pumped Tank 4:	Pumped
Do tanks need to be pumped? Yes No (If no provide measurements below)			Total Gallons Pum	nped: 2500	
			<u> </u>	pes not serve as a complia	nce inspection.
Visual Inspection (note any problems with the system): NOTE: This does not serve as a compliance inspection.					
·			•		
	*Tank Meas	urements-Use Onl	y If Tank(s) Were NO	OT Pumped	
Tank Length	in. X Tank Width	in. X Tank (Depth in, =	= Tank Volume (cubic inches	5)
Tank Radius	in. X Tank Radius	in. X 3.14	= Tank Volume (c	ubic inches)	
Tank Volume (cu. in.)	/ 231.01 =	Liquid Capacity	Gallons	Tank Depth in. = Gall	ons/Inch
Sludge Level	in. X Gallons Per Inch	= Sludge	Volume Gal	lons	
Scum Level	in. X Gallons Per Inch	= Scum V	olume Gal	lons	
Sludge Volume	+ Scum Volume	= Total Sl	udge and Scum Volur	me Gallons	
Total Sludge and Scu	m Volume /	Liquid Capacity	= Percer	at Sludge and Scum in Tank	%
Scum Layer Effluent Sludge Layer		fro	ank Depth measured om invert of outlet pe to bottom of tank	*Tanks must be pumped following conditions exist 1. The top of the sludge 12 inches from the botto baffle; or 2. Total sludge and scunthan 25 percent of the tocapacity.	st: layer is less than om of the outlet n volume is greate
Signature		Date	9/3/15	Rese	et Form