

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must | | | | | and refinit | |
|------------------------------------|------------------------------|--|--|-----------------------|--------------------|--|
| prior to pe | t be completed in its entire | ty to constitute a v | alid maintenance | permit. This permit | must be completed | |
| <u>prior</u> to pe | errorming maintenance activ | rities and remain o | n-site for the dura | ation of the maintena | nce activity. | |
| Date of Maintenar | nce: <u>(-29-20</u> Reason | on for Maintenance: | Boutine | | | |
| Property Address: | 355 Quinlan A | ie S | Property Owner's | Name: Wyrr | Jordahl | |
| Municipality: La | keland ZIP: 55 | Property Id | entification Numbe | r. | | |
| Maintenance Perm | nit No: 56447 C 1804 1 | Maintainer Name | and linear No. Bi | | | |
| | | manitainer Name a | and License No. Pin | ky's Environmental Se | wer Service/ L1673 | |
| Maintenance Performed | | Tank Mea | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | THE RESIDENCE OF THE PARTY OF T | Liquid Level of Tank — in | | | |
| \square Sludge and scum measured | | Sludge Level in | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No | (if no provide measurements | s) = % Sludge & So | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to | remove septage: Mainten | ance Hole Other | enter authorization o | rada) | | |
| | securely replaced? Yes | | and delibrization c | .ode) | | |
| | | | | | | |
| evidence of da | ce of tank leakage from a se | rolly uncound make | reatment or pump | tank below the oper | ating depth or | |
| | amaged, cracked, or structu | ratty unsound mair | itenance hole cove | ers? Yes No | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | * | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | ns of septage were removed | | | | | |
| Tank #1 /500 | gal Tank #2 | _gal Pretreatment | tankg | al Pump Tank | gal | |
| . Other information | on: List any troubleshooting | , minor repairs cor | nducted, tank safe | ty concerns, or other | Concerns | |
| | | | | , and the second | concerns. | |
| | | | | | | |
| . Location of septa | ge disposal: | | | | | |
| | | | | | | |
| | Pinky | 's Environmental Se | wer Service Inc. | | | |
| | | PO Box 35 | | | | |
| | | Afton MN 55 | 001 | | | |

Maintenance activities must be reported to the Department within 90 days.