

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a valid maintenance	permit. This permit must be complete
<u>prior</u> to performing maintenance activiti	es and remain on-site for the dura	ition of the maintenance activity
Date of Maintenance: 17-20 Reason	for Maintenance: Reutine	
Property Address: 1816 Demontre vill	CTIL Na Property Owner's I	Name: Brich + Jill Wiebe
Municipality: 444 Flmo zip: 5500	12 Property Identification Number	r·
Maintenance Permit Not Sh2611150163	-in-in-in-in-in-in-in-in-in-in-in-in-in-	
Maintenance Permit No 8036 W18063 M	aintainer Name and License No. <u>Pinl</u>	ky's Environmental Sewer Service/ L167
Maintenance Performed	Tank Measurement (must be	e completed if tanks NOT pumped)
Tank(s) Pumped	Liquid Level of Tank — in	The state of the s
☐ Sludge and scum measured		
Do tanks need to be pumped?	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100	
☐ Yes ☐ No (if no provide measurements)		AND CONTRACT OF THE PARTY OF TH
		anks must be pumped if 25% or greater
1. Access used to remove septage: Maintenance	ce Hole Other (enter authorization c	ode)
2. Were all covers securely replaced? Yes	No	
3. Is there evidence of tank leakage from a sept	ic, holding, pretreatment or pump	tank below the operating donth or
evidence of damaged, cracked, or structural	ly unsound maintenance hole cove	ers? Yes No
Tank	Leaking Out Leaking In	Cover Damage
Septic/Holding Tank #1	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
4. How many gallons of septage were removed?		11-12-12-12-12-12-12-12-12-12-12-12-12-1
Tank #1 Scc gal Tank #2g	al Pretreatment tank	al Pump Tank
o. Other information: List any troubleshooting, n	ninor renairs conducted, tank safet	ty concerns and the
. Location of septage disposal:		
District	Environmental Sewer Service Inc.	
Pinky's H	DVIronmental Cower Consider In-	

PO Box 354

Afton MN 55001