

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	ho completed in the con-			Carpenna et assault	and remine
prior to per	be completed in its entirety	to constitute a v	alid maintenance	permit. This permit n	nust be completed
<u> </u>	forming maintenance activit	ies and remain o	n-site for the dura	tion of the maintenan	ce activity.
Date of Maintenance	e: <u> - 9 - 20</u> Reason	for Maintenance:	Routine		
Property Address: 9			Property Owner's I	Name: Ken Ku	ittila.
Municipality: _ <i>S</i>	Il water ZIP: 550	8 Property Ide	entification Number	r·	
	111-1				_
	J. 5.41000 M	Maintainer Name a	ind License No. Pin	ky's Environmental Sev	ver Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintenan				23% of greater
3. Is there evidence	ecurely replaced? Yes of tank leakage from a septemaged, cracked, or structura	tic, holding, pret	reatment or pump tenance hole cove	tank below the opera	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐₩o	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
1. How many gallons	of septage were removed?	THE WHITE			
Tank #1 1500	gal Tank #2	gal Pretreatment	tankga	al Pump Tank	gal
. Other information	List any troubleshooting, i	minor repairs cor	ducted, tank safe	ty concerns, or other	concerns.
	Manhole to	o deep			
	2/0	,			
. Location of septage	e disposal: A Par				
	Pinky's	Environmental Se	wer Service Inc.		
		PO Box 35	4		

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001