

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entirety	to constitute a			- Cilille	
prior to per	be completed in its entirety	tios and remain	alid maintenance	permit. This permit	must be completed	
Data of Mili	forming maintenance activity	cies and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	e: <u>1-9-70</u> Reason	for Maintenance:	Keutius			
Property Address: \(\)	2363 100 5	St. No	Property Owner's I	Name: Mike	Mosper	
Municipality: St	Mulito ZIP:55	Property Id	ontification N	runc.	1000000	
Maintonanas Damii	w eluar 13326	- Froperty Ide	entification Number	r:		
Maintenance Permit	No: 36476417376	Maintainer Name a	and License No. Pinl	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintenar	nce Hole Other (enter authorization co	ode)		
	ecurely replaced? Yes			,		
	of tank leakage from a sep		reatment or numn	tank bolow the anam	-Ai I I	
evidence of dam	aged, cracked, or structura	ally unsound main	tenance hole cove	rs? Yes Wo	ating depth or	
	Tank	Leaking Out	Leaking In			
	Septic/Holding Tank #1			Cover Damage		
		Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
1. How many gallons	of septage were removed?		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Tank #1 /200	gal Tank #2	gal Pretreatment	tankga	l Pump Tank	ادم	
. Other information	: List any troubleshooting, i	minor repairs con	ducted, tank safet	V concerns, or other	Concerns	
_				, and the second	concerns.	
. Location of septage	e disposal:					
	Pinky's	Environmental Sev	wer Service Inc.			

PO Box 354

Afton MN 55001