

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must | be completed in its entirety | v to constitute a | valid maintana | | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | |
|------------------------------------|---|--|--|-----------------------|---------------------------------------|--|
| prior to per | forming maintenance activ | ities and remain o | n-site for the dur- | permit. This permit | must be completed | |
| Date of Maintenanc | e: 1-9-20 Passa | n for Maintenance: | Part the dura | ition of the maintena | ince activity. | |
| 1 | 10140 | . 0 | HUMILL | | | |
| Property Address: _ | 16-00 Orwe | | Property Owner's | Name: Tom Gr | chauck | |
| Municipality: W | me and a Crusto: 550 | M Property Id | entification Numbe | r: | | |
| Maintenance Permit | No: <u>£4747</u> y 17796 | Maintainer Name | and License No. Dim | | | |
| | | That is a second of the second | and License No. Pin | ky's Environmental Se | wer Service/ L1673 | |
| Maintenance Performed | | Tank Mea | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank — in | | | | |
| \square Sludge and scum measured | | | Sludge Level in Tank in | | | |
| Do tanks need to be pumped? | | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (| if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to re | emove septage: Maintena | | | in its mast be pumped | 11 25% or greater | |
| | securely replaced? \(\simega\) Yes | | enter authorization c | ode) | | |
| | | | | | | |
| evidence of dan | e of tank leakage from a sep naged, cracked, or structur | ally unsound main | reatment or pump | tank below the oper | ating depth or | |
| | | any ansound man | | ers? Yes No | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| 1. How many gallons | s of septage were removed? | | do son | | | |
| Tank #1 526 | gal Tank #2 | gal Pretreatment | tank ga | I Pump Tank | | |
| . Other information | n: List any troubleshooting, | minor repairs cor | ducted, tank safet | ty concerns or other | gal | |
| | | | and any current sure | ty concerns, or other | concerns. | |
| | | | | | | |
| . Location of septag | e disposal: | | | | | |
| | | | | | | |
| | Pinky's | Environmental Se | wer Service Inc | | | |
| | , | | TO SCIVICE IIIC. | | | |

PO Box 354

Afton MN 55001

P: 651-439-4847 license