

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location					
Address 7068 Consolvis	. Λ	7		Telephone Number	
1000 000012	• -	N ZIPSS		rty ID No./GEO Code	
1011agr 61602 1110					
Owner MINES HIESERICH Pumping Date 8/28/15 Contractor					
Maintainer MEYER SEWER MPCA License No. 915 Telephone Number 651-459-0162					
What was done to the system				Liquid Capacity in Gallons	
Dank(s) Pumped 7	•	Tank		Pumped Tank 2: /000	Pumped
Sludge and scum measured.		Tank	100	Pumped Tank 4:	Pumped
Do tanks need to be pumped?			Gallons Pumpe	·	
Yes No (If no provide measure	ements below)				
Visual Inspection (note any problems with the system): NOTE: This does not serve as a compliance inspection.					
*Tank Measurements-Use Only If Tank(s) Were NOT Pumped					
Tank Length in. X Tank Width	in. X Ta	ank Depth	in. = 1	Tank Volume (cubic inches)	
Tank Radius in. X Tank Radius	in. X 3	3.14 = Tan	k Volume (cubic	inches)	·
Tank Volume (cu. in.) / 231.0	D1 = Liquid Capac	ity	Gallons / Ta	ank Depth in. = Gallor	s/Inch
Sludge Level in. X Gallons Per Ir	nch = Sluc	ige Volume	Gallons	5	
Scum Level in. X Gallons Per Ir	nch = Scu	m Volume	Gallons	5	•
Sludge Volume + Scum Volum	e = Tota	- al Sludge and	Scum Volume	Gallons	
Total Sludge and Scum Volume	/ Liquid Capaci	-		udge and Scum in Tank	%
Scum Layer Effluent Sludge Layer		Tank Depth from invert pipe to bot		*Tanks must be pumped if following conditions exist: 1. The top of the sludge lay 12 inches from the bottom baffle; or 2. Total sludge and scum v than 25 percent of the tank capacity.	er is less than of the outlet olume is greater
Signature /	ر ا	Date 8	128/15	Reset F	orm