

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

	4	Syste	em Location			
Address 7115 Granade Au S		5	Telephone Number			
City Cottage	Gare	State	N ZIPSSON	6 Property I	D No./GEO Code	
Owner Ron S	Sher	Pumping	Date 11/19/1	'S .		
			ontractor			
Maintainer MEY	ER SEWEI	MPCA Lice	ense No. 914	Telep	phone Number 65	1-459-0162
What w	s done to the syste	m?		Report Liq	uld Capacity in Gal	ons
Tank(s) Pumped			Tank 1: /2	200 X Pui	mped Tank 2:	Pumpe c
Sludge and scum measured.			Tank 3:		mped Tank 4;	Pumperd
Do tanks need to be pumped? Yes No (If no provide measurements below)			Total Gallons Pumped: 1200			
						
visual inspection	note any problems	with the system):	NOIE:	This does not	serve as a compli	ance inspection
	*Tank	Measurements-Use	Only If Tank/s) M	Jore NOT Pum	ned	
Tank Length	in. X Tank Width		·		Volume (cubic inche	ac)
Tank Radius	in. 🗶 Tank Radiu -	s in. X 3	.14 = Tank Vol	ume (cubic incl	nes)	•
Tank Volume (cu. in.	/ 231	.01 = Liquid Capac	ity G	Sallons / Tank (Depth in. = Ga	llons/Inch
Sludge Level	in. X Gallons Per	Inch = Slud	lge Volume	Gallons		
Scum Level	in. X Gallons Per	Inch = Scur	m Volume	Gallons		
Sludge Volume	+ Scum Volur	ne = Tota	I Sludge and Scun	n Volume	Gallons	
Total Sludge and Sci	ım Volume	Liquid Capacit	ty=	Percent Sludge	e and Scum in Tank	%
Scum Layer Effluent Sludge Layer			Tank Depth mea from invert of ou pipe to bottom o	follows follow	nks must be pumper owing conditions exite top of the sludge inches from the botter; or otal sludge and scurn 25 percent of the tracity.	ist: layer is less than om of the outlet n volume is greate