

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

			Sys	item Location		·	<u> </u>
Address 7680	La	naley to	ک ہے	· · · · · · · · · · · · · · · · · · ·		Telephone Number	
City Co Hage	Gra			MU ZIPSSOW	, Prop	perty ID No./GEO Code	
Owner Veff	D'a	le.		ig Date ///g//s			
	70		(Contractor			
Maintainer MEY	ER S	EWER	MPCA Li	cense No. 914	5	Telephone Number 65	1-459-016
What was done to the system?				Report Liquid Capacity in Gallons			
Tank(s) Pumped				Tank 1: /son Pumped Tank 2: Pumper			
Sludge and scum measured.				Tank 3;		Pumped Tank 4:	Pumped
Do tanks need to be pumped? Yes No (If no provide measurements below)				Total Gallons Pumped: 1500			
Visual Inspection		**************************************		L		s not serve as a compli	ance inspection
		*Tank Meas	urements-Us	e Only If Tank(s) V	Vere NOT	Pumped	
Tank Length	in. X	Tank Width	in. X T	fank Depth	in. =	Tank Volume (cubic inche	s)
Tank Radius	in. X	Tank Radius	in. X	3.14 = Tank Vol	ume (cubi	ic inches)	
Tank Volume (cu, in.	-) - -	/ 231.01 =	Liquid Capa	icity (Sallons / T	fank Depthin. = Gal	lons/Inch
Sludge Level	in. X	Gallons Per Inch	= SIc	udge Volume	Gallon	ns	
Scum Level	in. X	Gallons Per Inch	= Sci	um Volume	Gallon	15	
Sludge Volume	+	Scum Volume	= To	tal Sludge and Scur	— ກ Volume	Gallons	
Total Sludge and Sci	um Volu	me/	Liquid Capac	city =	Percent S	ludge and Scum in Tank	95
Scum Layer Effluent Sludge Layer				Tank Depth mea from invert of ou pipe to bottom	utlet	*Tanks must be pumped following conditions exist. The top of the sludge 12 inches from the botto baffle; or 2. Total sludge and scunthan 25 percent of the trapacity.	st: layer is less than om of the outlet n volume is greate