DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 7-18-17 Reaso	n for Maintenance:),M ,		
Property Address: 15375 TR	Sh Ave Prop	perty Owner's Name:	oug alson	
Municipality: Hugs	State NN Zip Coo	de 55038 GEO C	ode/Property I.D. #: USIZ6+698	
What was done to the system?	Tank Me	Tank Measurements (must be completed if tanks NOT pumped)		
Tank(s) Pumped	Liquid Level of Ta	in Studen	lovel in Soundard in	
Sludge and scum measured.	Liquid Level of Ta	ink in. Sludge	Level in. Scum Level in.	
Do tanks need to be pumped? Yes No (If no provide measureme	Total (Sludge + So	cum) / Liquid Le	evel = % Sludge & Scum	
- (3			* Tank must be pumped if this value	
1. Access used to remove septage: Maint		1	is greater than 25%.	
2. If maintenance hole was used, were all cover	rs securely replaced?	es No please exp	plain	
Explanation:	5			
3. If owner refuses to allow a Subsurface Se them complete and sign the following sta	wage Treatment Syste tement:	m (SSTS) to be pumped	through the maintenance hole, have	
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance				
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example				
Tank#1 Yes No Verificatio Metho	d Used:			
Tank#2 Yes No Verificatio Metho	d Used:			
5. Is there evidence of tank leakage from a s damaged, cracked, or structurally unsoun	eptic, holding, pretrea	tment or pump tank be	low the operating depth or evidence of	
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes KNo	Yes YNo	
Septic/Holding Tank #2	☐ Yes ►No	☐ Yes ♥No	Yes No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
6. How many gallons of septage were remov	ed?			
Tank #1 Tank #2 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooting	ng, minor repairs cond	ucted, tank safety conc	erns, or other concerns.	
8. Certification: I hereby certify as a State of N and made the observations, c	linnesota certified SSTS or directly supervised otl	Maintainer that I persona ners in the performance o	lly conducted the work f this job.	
Maintainer's Name: OCSON Source	Maintaine	er's Address: 1763	8 Your ST N.E.	
Maintainer's License #: Maintainer's Phone #: 651-464-2692				
Maintainer's Signature Date: 7-18-17				