

Soil Observation Log

Project ID:

v 04.01.2019

Client: **Richard and Wendy Gagne** Location / Address: **11373 Neal Ave S**

Soil parent material(s): (Check all that apply) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Vegetation: **Lawn** Soil survey map units: Slope %: **5.0** Elevation:

Weather Conditions/Time of Day: **Bright sunny day 2:00 p.m.** Date: **03/03/20**

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Observation Type:		
							Shape	Grade	Consistence
0-24"	Silt Loam	<35%	10YR 4/4						Auger
24-49"	Loamy Fine Sand	<35%	10YR 5/4						
49-65"	Silt Loam	<35%	10YR 5/6						
65 - 84"	Silt Loam	<35%	10YR 5/4						

Observation #/Location: See attached map of system

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

S. Schlonka (Designer/Inspector)  (Signature) **1106** (License #) **3/3/2020** (Date)