DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 3/11/20 Reason for	Maintenance:	Repair V41	1469 18023
Property Address: 16463 Harrow F	E 7	17	Jave Anderson
Municipality: Hugo s	tate MV Zip Coo	e <u>55038</u> GEO C	ode/Property I.D. #:
What was done to the system?	Tank Me	asurements (must be co	ompleted if tanks NOT pumped)
☐ Tank(s) Pumped ☐ Sludge and scum measured.	Liquid Level of Ta	nk in. Sludge	Level in. Scum Level in.
Do tanks need to be pumped? Yes No (If no provide measurements)	Total (Sludge + So	um) / Liquid Le	evel = % Sludge & Scum
1. Access used to remove septage:	ce Hole :Other	(Go to #3 below)	 * Tank must be pumped if this value is greater than 25%.
2. If maintenance hole was used, were all covers se	curely replaced?	≺ Yes ☐ No <i>please exp</i>	
Explanation:		•	
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem	e Treatment Systement:	m (SSTS) to be pumped	through the maintenance hole, have
l, (own	er's name), refuse to	allow the removal of soli	ids and liquids through the maintenance
hole. I understand that removal of solids and liq			•
4. Is the tank designed as a leaky tank? example: see	epage pit, cesspool, a	lrywell, leaching pit	
Tank#1 Yes No Verificatio Method Us	ed: Visua	J	
Tank#2 Yes No Verificatio Method Us	ed: Visue	el	
5. Is there evidence of tank leakage from a septi damaged, cracked, or structurally unsound m	c, holding, pretrea	tment or pump tank be	low the operating depth or evidence of
Tank	Leaking Out	Leaking In	Cover Damage
	Yes No	Yes No	☐ Yes ☒ No
	Yes X No	厂 Yes 区 No	☐ Yes 下No
Pretreatment Tank	Yes No	Yes No	Yes No
Pump Tank	Yes X No	Yes No	☐ Yes 🔀 No
6. How many gallons of septage were removed?			
Tank#1 1000 Tank#2 1000	Pretreatment Ta	nk P	ump Tank <u>250</u>
7. Other information: List any troubleshooting,	minor repairs cond	ucted, tank safety conc	erns, or other concerns.
8. Certification: I hereby certify as a State of Minn	esota certified SSTS	Maintainer that I persona	ally conducted the work
and made the observations, or di	rectly supervised ot	ners in the performance o	of this job.
Maintainer's Name: OSST	rectly supervised ot	ners in the performance of	of this job. 8 Lyons St. NE
Maintainer's Name: OSST	rectly supervised ot Maintain	ners in the performance of	25