

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety ming maintenance activiti					
Date of Maintenance:	7-15-20 Reason	for Maintenance:	Ranna		1	
	10 Jamaca		•	me: Stan	Hauser	
Municipality: <u>(W/</u>	Elmo zip:550	42 Property Ider	tification Number:			
Maintenance Permit N	:P6521218077 A	Maintainer Name an	d License No. <u>Pinky</u>	r's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank ———— in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes Yes						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 /500	of septage were removed gal Tank #2 List any troubleshooting	_gal Pretreatment				
6. Location of septage	disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673