



Client/ Address:		10524 Kimbro Ave			Legal Description/ GPS:			2.60272E+12		
Soil parent material(s): (Check all that apply)										
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Foot Slope		<input type="checkbox"/> Toe Slope		Slope shape
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Loess		<input type="checkbox"/> Till		<input type="checkbox"/> Alluvium		<input type="checkbox"/> Bedrock
<input type="checkbox"/> Organic Matter										
Landscape Position: (check one)										
Lawn		Soil survey map units			Slope%		Elevation:		Date	
									04/01/20	
Weather Conditions/Time of Day: Sunny 4:00										
Observation #/Location: 2' outside of STA between both lines - see map										
Observation Type: Auger										
Texture			Rock Frag. %		Matrix Color(s)		Mottle Color(s)		Indicator(s)	
0-24"			<35%		10YR 4/2					
24-48"			<35%		7.5YR 4/4					
48 - 72"			<35%		7.5YR 4/6					
Comments										
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.										
Shelley Schlomka					1106			#REF!		4/1/2020
(Designer/Inspector)					(Signature)			(License #)		(Date)