DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Pate of Maintenance 4 Reason	for Maintenance:	24434:18m	176		
Property Address: 22797 Domper	vial Al. Prop	erty Owner's Name:	ante Brandt		
Municipality: Frest Jalu	State Zip Cod	e 55125 GEO	ode/Property I.D. #:		
What was done to the system?	Tank Me	asurements (must be co	ompleted if tanks NOT pumped	I)	
Tank(s) Pumped					
Sludge and scum measured.	Liquid Level of Tai	Liquid Level of Tank in. Sludge Level in. Scum Level in.			
Do tanks need to be pumped?	Total (Chidae - Ca	Total (Sludge + Scum) / Liquid Level = % Sludge & Scum			
Yes No (If no provide measuremen	nts)	um) / Liquid Le	evel = % Sludge & Scun	1	
1. Access used to remove septage: Mainte			* Tank must be pumped if the is greater than 25%.	nis value	
2. If maintenance hole was used, were all cover	s securely replaced?	Yes No please exp	plain		
Explanation:					
3. If owner refuses to allow a Subsurface Sew them complete and sign the following stat	vage Treatment System tement:	n (SSTS) to be pumped	through the maintenance hole	, have	
l,(o	wner's name), refuse to	allow the removal of sol	ids and liquids through the main	tenance	
hole. I understand that removal of solids and	l liquids through other a	ccess points is not consi	dered maintenance.		
4. Is the tank designed as a leaky tank? example	: seepage pit, cesspool, d	rywell, leaching pit			
Tank#1 Yes No Verificatio Method	l Used:				
Tank#2 Yes No Verificatio Method	Used:				
5. Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound	eptic, holding, pretreat	ment or pump tank be	low the operating depth or evi	dence of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	Ti Yes No	Yes No	X		
Septic/Holding Tank #2	☐ Yes 🗆 No	The same of the sa	Yes No		
Pretreatment Tank	☐ Yes ☐ No	Yes No	Yes No		
Pump Tank		Yes No	Yes No		
	Yes No	Yes No	Yes No		
6. How many gallons of septage were remove Tank #1 1000 Tank #2 1000		ok D	uman Tank		
			ump Tank <u>650</u>		
7. Other information: List any troubleshootin	g, minor repairs condu	icted, tank safety conc	erns, or other concerns.		
8. Certification: I hereby certify as a State of Mi and made the observations, or	r directly supervised oth	ers in the performance o	f this job.		
Maintainer's Name: 1500 Sewer			Lyons St NE		
Maintainer's License #: Maintain	ner's Phone #: 651-4	64-2082			
Maintainer's Signature	<i>A</i>		-20,2026		