## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	ance 10-13-15 Reason f	for Maintenance:	outine			
Property Address	5:3643 Norsta	od Ave S Property	Owner's Name: To	ny Reber		
Municipality:	AFton	State MD Zip Code _	GEO Cod	e/Property I.D. #:		
What w	as done to the system?	Tank Measur	ements (must be com	pleted if tanks NOT pump	ed)	
Do tanks nee	cum measured. ed to be pumped?	Liquid Level of Tank - Total (Sludge + Scum)	in. Sludge Le		in. * um	
	No (If no provide measuremen			* Tank must be pumped i	f this value	
	remove septage: Mainte			is greater than 25%.		
2. If maintenance	e hole was used, were all cover	s securely replaced?	es   No piease expia	in		
Explanation:						
	ses to allow a Subsurface Sew te and sign the following stat		STS) to be pumped th	rough the maintenance h	ole, have	
1,	(0	wner's name), refuse to allo	ow the removal of solid:	s and liquids through the ma	aintenance	
hole. I unders	tand that removal of solids and	l liquids through other acce	ess points is not conside	ered maintenance.		
4. Is the tank des	igned as a leaky tank? example	e: seepage pit, cesspool, dryw	ell, leaching pit			
Tank#1 🔲 Y	es No Verificatio Method	d Used:				
Tamk#3 [TV	es No Verificatio Method					
Tank#2 Y	Security .		ent or numn tank hole	w the operating depth or	evidence of	
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	Yes No	T Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No		
6. How many ga	allons of septage were remov	red?				
Tank #1 12	S	Pretreatment Tank	Pretreatment Tank Pum		mp Tank	
7. Other inform	ation: List any troubleshooti	ng, minor repairs conduc	ted, tank safety conce	erns, or other concerns.		
8. Certification	: I hereby certify as a State of I and made the observations,	Minnesota certified SSTS Ma or directly supervised other	aintainer that I persona rs in the performance o	lly conducted the work f this job.		
Maintainer's I	Name: PINKY'S SEWER SERVICI	E Maintainer's	s Address: P.O. Box 354	Afton, MN 55001		
Maintainer's I	License #: 1673 Maint	ainer's Phone #: 651-439-4	1847			
Maintainer's	Signature //	ara 2	Date: ノロ	2-13-15		