DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Mainte	Prinance 439 Reason Reason	on for Maintenance:	K 6531 x	18088	
Property Addre	ess: 6460 -125 th	St. Pro	perty Owner's Name:	ally Hemand	
Municipality:	Dugo WBL	State MN Zip Co	de <u>55110</u> GEO C	ode/Property I.D. #:	
1	was done to the system?	Tank Mo	easurements (must be co	ompleted if tanks NOT pumped)	_
Tank(s) Pumped		Liquid Level of Ta	ink in Sludge	Level in Scum Level	-
	scum measured.	Liquid Cevel Of 18	iii. Sluage	Level in. Scum Level	n.
I	eed to be pumped? No (If no provide measurem	Total (Sludge + S	cum) / Liquid Le	vel = % Sludge & Scum	
					_
	to remove septage: Main			 Tank must be pumped if this value is greater than 25%. 	ue
2. If maintenand	ce hole was used, were all cov	ers securely replaced?	Yes No please exp	lain	
Explanation:		/			
3. If owner refu them comple	uses to allow a Subsurface So te and sign the following st	ewage Treatment Syste atement:	m (SSTS) to be pumped	through the maintenance hole, have	-
1,		(owner's name), refuse to	allow the removal of soli	ds and liquids through the maintenan	
hole. Lunders	stand that removal of solids ar	nd liquids through other	access points is not consid	dered maintenance.	Le
	signed as a leaky tank? examp				
Tank#1 🗀 Y	es No Verificatio Metho	od Used:			
Tank#2 TY	es No Verificatio Metho	od Used:			
5. Is there evide damaged, cra	ence of tank leakage from a icked, or structurally unsou	septic, holding, pretrea nd maintenance hole co	tment or pump tank bel	ow the operating depth or evidence	: O
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes X No	Yes K No	
Pole Born	Septic/Holding Tank #2	Yes No	☐ Yes ☑ No	☐ Yes ☑ No	
	Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
	Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
6. How many ga	llons of septage were remo	ved?	Volta Compre		
Tank #1 // 5	Pole Bari		ink Di	uma Tank	
(1.0				ump Tank	
7. Other informa	ation: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conce	erns, or other concerns.	
3. Certification:	I hereby certify as a State of I and made the observations,	Minnesota certified SSTS or directly supervised otl	Maintainer that I personal ners in the performance o	lly conducted the work f this job.	_
	ame: Olson Sewa		er's Address: 17638	Lyons St NE	
Maintainer's Li	cense #: Alb Mainta	ainer's Phone #: 651-	464-2082	-	
Maintainer's Si	gnature	Pl	Date: 4	- 30-2020	