

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance r	ermit. This permit n	nust he completed	
prior to performing maintenance activit	ies and remain o	n-site for the dura	tion of the maintenar	ice activity	
Date of Maintenance: $\frac{4-23-2c}{}$ Reason	for Maintenance:	Ratiu	l	or activity.	
Property Address: 16595 4t St.	Mo	Property Owner's N	lame: Jeff S	stenten	
114		entification Number			
Maintenance Permit No: C9812 K18856 N	Naintainer Name a	and License No. Pink	v's Environmental Co.		
		The Electise No. 1 III	s chivironinientat sev	ver Service/ L16/3	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
2. Were all covers securely replaced? Yes 2. 3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura Tank	ic, holding, pret	reatment or pump	tank below the operars? Yes No	ting depth or	
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 250 gal Tank #2 Other information: List any troubleshooting, r	gal Pretreatment	tankga	l Pump Tank	gal	
. Location of septage disposal:					
			MATERIAL PROPERTY.		

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673

P: 651-439-4847 License