DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance	son for Maintenance:	du #	9116/8803	
Property Address: 14855 Cla	Tholando To Pro	operty Owner's Name:	Frank Vaugha	
Municipality:	State Zip Co	ode GEO	Code/Property I.D. #:	
What was done to the system?	Tank M	easurements (must be	completed if tanks NOT pr	ımped)
☑ Tank(s) Pumped				iniped/
Sludge and scum measured.	Liquid Level of T	ank in. Slud	ge Level in. Scum Le	evel in.
Do tanks need to be pumped?	Total (Sludge + S	Scum) / Liquid	iousi — 0/61 t	
Yes No (If no provide measuren	nents)	icum) / Liquid	Level = % Sludge	& Scum
	ntenance Hole Othe		* Tank must be pump	ed if this value
2. If maintenance hole was used, were all cov	ers securely replaced?		is greater than 25%.	
Explanation:	/	,5		
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Syste	em (SSTS) to be pumpe	d through the maintenance	e hole, have
4		*		
hole. I understand that removal of solids at	nd liquids through other	allow the removal of s	olids and liquids through the	maintenance
4. Is the tank designed as a leaky tank? examp	ole: seenage nit cessool	decess points is not con	sidered maintenance.	
<u>-</u>		aryweii, ieaching pit		
Tank#1 Yes No Verificatio Metho	od Used:			
Tank#2 Yes No Verificatio Metho	od Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsoul	septic, holding, pretrea	tment or pump tank b	elow the operating depth o	or evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	T Yes No		_
Septic/Holding Tank #2	Yes No	T Yes No	Yes No	
Pretreatment Tank	Yes No	TYes TNo	Yes No	_
Pump Tank	Yes No	Yes No	Yes No	-
i. How many gallons of septage were remov	ved?	2.3 100 2.110	IE3 IAO	-
Fank#1 1050 Tank#2 500	Pretreatment Ta	nk	Pump Tank	
. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety con	cerns, or other concerns.	
Certification horoby contife as a Change	A+			
. Certification: I hereby certify as a State of N and made the observations, o	/IInnesota certified SSTS . Or directly supervised off	Maintainer that I person	ally conducted the work	
Maintainer's Name: OSD Sture	-	r's Address: (763	8 to 1 can (St	NE
Maintainer's License #: Mainta	iner's Phone #: 6514	472082	- CAUND /	1
Maintainer's Signature		Date:	3.7.20	
- U				