DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance Reas	on for Maintenance.	m78394 18784		
Property Address: 18681 Olimbia	Pro Pro	perty Owner's Name	marshal in	
Municipality:	State M Zip Co	ode 550-7 GEO	Code/Property I.D. #:	
What was done to the system?	Tank M	easurements (must be c	ompleted if tanks NOT pum	ped)
Tank(s) Pumped				
Sludge and scum measured.	Liquid Level of T	ank in. Sludge	Level in. Scum Leve	el in.
Do tanks need to be pumped? Yes No (If no provide measurem	Total (Sludge + S	icum) / Liquid Le	evel = % Sludge & S	icum
1. Access used to remove septage: Main			 * Tank must be pumped is greater than 25%. 	if this value
2. If maintenance hole was used, were all cov	ers securely replaced?	Yes No please exp	plain	
Explanation:	(
3. If owner refuses to allow a Subsurface Set them complete and sign the following st	ewage Treatment Systematement:	em (SSTS) to be pumped	through the maintenance h	ole, have
l,	'Owner's name) refere	a allacost		
hole. I understand that removal of solids ar	id liquids through other	allow the removal of sol	ids and liquids through the m	aintenance
4. Is the tank designed as a leaky tank? examp	le: seepaae pit. cesspool.	drivell leaching nit	dered maintenance.	
Tank#1 Yes No Verificatio Metho		ary wear, redefining pit		
Tank#2 Yes No Verificatio Metho	nd Used-			
Is there evidence of tank leakage from a s damaged, cracked, or structurally unsour	id maintenance hole c	ntment or pump tank be overs?	low the operating depth or	evidence of
Tank	Leaking Out	Leaking in	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
6. How many gallons of septage were remov	red?		-	
Tank #1 1350 Tank #2	Pretreatment Ta	ank Pu	ump Tank	
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	erns, or other concerns	
-		,		
3. Certification: I hereby certify as a State of N and made the observations, o	Minnesota certified SSTS or directly supervised of	Maintainer that I persona	lly conducted the work	
Maintainer's Name:		er's Address:	R Lynns St	L F
Maintainer's License #: Mainta	iner's Phone #: 65 (4042082	A COURT OF	
Maintainer's Signature		Date: <u>5</u>	7-20	