

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	o completed in the second				The state of the s	
prior to perf	e completed in its entiret	y to constitute a v	alid maintenance	permit. This permit	must be complete	
prior to perio	orning maintenance activ	ities and remain o	n-site for the dura	tion of the maintena	ince activity.	
Date of Maintenance	: <u>И-21-20</u> Reason	n for Maintenance:	Routiu	2		
Property Address: 1	0360 July	me Ct. U.	Property Owner's	Name: Denny *	Terni	
Municipality: Styll	uutu zip:550	87 Property Ide	entification Numbe	r.	Weiler	
Maintenance Permit	111-1 1000			9) -4.4.		
	1000	manitamer Name a	nd License No. Pin	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		The second secon	Liquid Level of Tank ——— in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		H .	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rea	move septage: Maintena	ince Hole Other (11 25% of greater	
3. Is there evidence	ecurely replaced? Yes of tank leakage from a sep aged, cracked, or structur	otic, holding, preti	reatment or pump tenance hole cove	tank below the operers? Yes No	ating depth or	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed:					
Tank #1 1500	gal Tank #2	_gal Pretreatment	tank ga	al Pump Tank	gal	
5. Other information:	: List any troubleshooting,	minor repairs con	ducted, tank safe	ty concerns or other	gat	
					concerns.	
-						
. Location of septage	disposal:					
	Pinky's	s Environmental Se	wer Service Inc.			
		PO Box 354				
		Afton MN 550	001			

Maintenance activities must be reported to the Department within 90 days. The reported to

1: 65T-439-486/ License