

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	bo complete die tr				iance remit	
prior to per	be completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be completed	
	similarite ratio	ricies and remain o	n-site for the dura	ation of the maintena	nce activity.	
Date of Maintenance	e: <u>4-20-20</u> Reason	on for Maintenance:	Reutino			
Property Address: \frac{1}{2}	1930 Pertrillage	e Rel Ct. Le	Property Owner's	Name: Trucu * C	nistral	
Municipality: Sti	Illucto ZIP: 55	SOSZ Property Ide	entification Numbe	r:	Cricker	
Maintenance Permit	No: <u>\$5541h 18898</u>	Maintainer Name	and License No. Dis			
- 1		Traine t	ind License No. Pin	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured		III .	Sludge Level in Tank in Source Level in Tank			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)) = % Sludge & Sc	A. A			
				anks must be pumped	if 25% or greater	
	emove septage: Mainten		enter authorization of	ode)		
2. Were all covers s	ecurely replaced? 🗌 Yes	□No				
Is there evidence	of tank leakage from a se	ptic, holding, preti	reatment or pump	tank below the oper	ating donth as	
evidence of dam	naged, cracked, or structu	rally unsound main	tenance hole cove	ers? Yes No	acing depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed	?				
Tank #1 /200	gal Tank #2	gal Pretreatment	tank g	Dumm Taul		
. Other information	: List any troubleshooting	minor renairs con	dusted tank and	at Pump Tank	gal	
manhole unde	- Sitemalle/ Jamascapi	ks	ducted, tank safe	ty concerns, or other	concerns.	
10.00			A HOLDEN			
. Location of septage	e disposal:				17	
	Pinky'	s Environmental Car				
	FIIIKY	s Environmental Sev				
		PO Box 354	1			

P: 651-439-4847 License Number: L1673

Afton MN 55001

P: 651-439-4847 License Ni