

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	y to constitute a v	alid maintenance	permit This permit		
This section must be completed in its entirety prior to performing maintenance activity	ities and remain o	n-site for the dura	tion of the maintena	nust be completed	
Date of Maintenance: 4-17-20 Reason	n for Maintenance:	Rutius	ion of the maniterial	ice activity.	
Property Address: 4477 Northbro	ek Blu	Property Owner's N	Name: Cent Gro	nalliensal	
Municipality: Stillwato zip: 55	SZ Property Ide	entification Number			
Maintenance Permit No: 05900 18881	Maintainer Name a	nd License No. Diel			
	Maritanier Name a	ild License No. Pink	<u>sy's Environmental Sev</u>	ver Service/ L1673	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks I	NOT pumped)	
Tank(s) Pumped	Liquid Level of Tank — in				
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum	The state of the s			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structure. Tank	ally unsound main	tenance hole cove	rs? Yes No Cover Damage	tering depth of	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No				
		☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
Pretreatment Tank Pump Tank	☐ Yes ☐ No				
Pump Tank 4. How many gallons of septage were removed?	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
Pump Tank 4. How many gallons of septage were removed? Tank #1 1250 gal Tank #2 5. Other information: List any troubleshooting,	Yes No gal Pretreatment minor repairs con	☐ Yes ☐ No ☐ Yes ☐ No tankga	Yes No Yes No Pump Tank y concerns, or other	concerns.	
Pump Tank 4. How many gallons of septage were removed? Tank #1 250 gal Tank #2 5. Other information: List any troubleshooting,	Yes No gal Pretreatment minor repairs con	☐ Yes ☐ No ☐ Yes ☐ No tankga	Yes No Yes No Pump Tank y concerns, or other	concerns.	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

ATTOR MIN 550

P. 651-439-4847 license