

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be co	mpleted in its entiret	y to constitute a v	alid maintenance p	permit. This permi	t must be complete	
prior to performi	ng maintenance activ	ities and remain o	n-site for the dura	tion of the mainten	ance activity.	
Date of Maintenance: 💃						
Property Address: 629	19 Iceswill	(Are No	Property Owner's N	lame: Lee G	Mespre	
Municipality: Silve	Uto ZIP: 55	2 Property Ide	entification Number			
Maintenance Permit No:	1988/918891	Maintainer Name a	and License No. Pink	v's Environmental 6		
/ 1				y 3 Environmental 3	sewer service/ L16/s	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		A THE RESIDENCE AND ADDRESS OF THE PARTY OF	Liquid Level of Tank ——— in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? — Yes — No (if no provide measurements)			Sludge + Scum / Liquid Level X 100			
		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove	e septage: Maintena	ince Hole Other (
2. Were all covers secure	ely replaced? Yes	□ No.	ones additionization co	ide) Take (n Thi	a sailain	
3. Is there evidence of ta			reatment or nume	4		
evidence of damaged	, cracked, or structur	ally unsound main	tenance hale cover	tank below the ope	erating depth or	
		- , and and man		is: L res L No		
_	Tank	Leaking Out	Leaking In	Cover Damage		
Sep	otic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Sep	otic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pre	treatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pur	np Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of se				A CONTRACTOR OF THE PARTY OF TH		
Tank #1 12 5D ga	l Tank #2	_gal Pretreatment	tankga	l Pump Tank	gal	
5. Other information: List	any troubleshooting,	minor repairs cor	ducted, tank safet	v concerns or othe	er concerns	
				,	er concerns.	
		1				
6. Location of septage disp	osal:5	Tall .				
	Pinky's	s Environmental Se	wer Service Inc.			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001

P: 651-439-4847 License Number: L1673

Alton MN 55001

P: 651-439-4847 License No.