

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety $\frac{\text{prior}}{\text{to performing maintenance activity}}$ Date of Maintenance: $\frac{4-16-20}{\text{Reason}}$ Reason	ties and remain on-	site for the durat		7	
Property Address: 3104 Octobale	and the same of th		ame: Robin	Beckwith	
Municipality: Pine springs ZIP:	Property Iden	tification Number:			
Maintenance Permit No: V 2037018843				ewer Service/ L167	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank ——— in				
☐ Sludge and scum measured	Sludge Level in T	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements) = % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure ————————————————————————————————————				rating depth or	
Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed Tank #1 \(\sum_{\infty} \) gal \(\tank \) #2		tank ga	al Pump Tank	, aal	
5. Other information: List any troubleshooting 6. Location of septage disposal:	g, minor repairs con	ducted, tank safe	ty concerns, or oth		

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

ANT. ARD. ANAT Licenses