

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED I	THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER, THE					
Date of Maintenance:	5/19/20 Reason	for Maintenance:	Thoute	<		
Property Address:/	3490 St. CA	XTIIN	Property Owner's N	lame: Phic We	endt	
Municipality:	woter ZIP: 550	od Property Ide	ntification Number	•		
	0: E 973817627 N				12428	
	1,067	name and	id Electise No. Simi	TIC 3 SCWCI SCIVICE	LZ4ZO	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☐ Tank(s) Pumped☐ Sludge and scum measured		Liquid Level of Tank in				
		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
$lue{}$ Yes $lue{}$ No (if no provide measurements)		3 Staage a Set	- % studge a scalin rails must be pumped if 25% of greater			
1. Access used to remove septage: Aaintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? ✓ Yes ☐ No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or						
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes						
				103 12110	,	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes ☑No		
	Pump Tank	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes ☐No		
	of septage were removed					
Tank #1_800	_ gal Tank #2 <u>500</u>	gal Pretreatmen	tank	al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
6. Location of septage	e disposal:	Lund	Amlina			

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073

License# 2428 P: 651-433-3934