

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entirety	to constitut	1.1		- Crimic
prior to per	be completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be completed
Date of Maintana	forming maintenance activit	ties and remain o	n-site for the dura	ation of the maintena	nce activity.
Date of Maintenance	re: 4-16-2c Reason	for Maintenance:	Koutine		
Property Address:	1202 244 St. W		Property Owner's	Name: Freel Fe	· · · · · · · · · · · · · · · · · · ·
Municipality: Lak	ce Elmo ZIP:		entification Numbe		cer vizin
Maintenance Permit		rroperty id	entification Numbe	r:	
	t No: <u>C2341W18880</u> A	Maintainer Name a	and License No. Pin	ky's Environmental Se	ewer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank			
Do tanks need to be pumped?		Sludge + Scum			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintenan			miks must be pumped	11 25% or greater
2 Word all covers	maintenan	other (enter authorization c	ode)	
3. Is there evidence	securely replaced? Yes	□ No 11	flower ga	rden	
evidence of dan	of tank leakage from a sept	tic, holding, pret	reatment or pump	tank below the oper	ating depth or
evidence of dan	naged, cracked, or structura	lly unsound main	tenance hole cove	ers? 🗌 Yes 🖾 No	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons	s of septage were removed?				
Tank #1 15 0	gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal
. Other information	n: List any troubleshooting, r	minor repairs con	ducted, tank safet	V concerns or other	gat
				, concerns, or other	concerns.
. Location of septage	e disposal:				
Location of septag	e disposal:				
Location of septage					
Location of septage		Environmental Se PO Box 354	wer Service Inc.		

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001

P: 65T-439-4847 License

P: 651-439-4847 License Number: L1673