## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

| Date of Maintena           | nce 10-30-15 Reason  | for Maintenance:                            | outine                  |   |   |
|----------------------------|--|---|-------------------------|---|---|
| Property Address           | :58910 Lake J  | ine TLID Property                           | Owner's Name:           | et Lannin                                     | 9                                       |
| Municipality: 1            | olle Elmo  | State M Zip Code                            | GEO Cod                 | e/Property I.D. #:                            | <u> </u>                                |
| , What wa                  | as done to the system?   | Tank Measur                                 | ements (must be com     | pleted if tanks NOT pumpe                     | d)                                      |
| <del>-</del>               | ed<br>tum measured.<br>d to be pumped?<br>No (If no provide measuremer | Liquid Level of Tank  Total (Sludge + Scum) | in. Sludge Le           | <del></del>                                   | in.<br>#<br>                            |
| 1. Access used to          | remove septage: Mainte   | nance Hole Other (Go                        | to #3 below)            | * Tank must be pumped if is greater than 25%. | this value                              |
|                            | hole was used, were all cover  |   |                         | -   |   |
| Explanation:               |  |   |                         |   |   |
| 3. If owner refus          | es to allow a Subsurface Sev<br>e and sign the following sta           | wage Treatment System (S<br>tement:         | STS) to be pumped th    | rough the maintenance ho                      | le, have                                |
| l,                         |  |   |                         | s and liquids through the ma                  | intenance                               |
|                            | and that removal of solids and   |   |                         | ered maintenance.                             |   |
| <b>4.</b> Is the tank desi | igned as a leaky tank? <i>exampl</i> e                                 | e: seepage pit, cesspool, dryw              | ell, leaching pit       |   |   |
| Tank#1 🔲 Ye                | es TINO Verificatio Metho  | d Used:                                     |                         | •   |   |
| Tank#2 Ye                  | es No Verificatio Metho  | d Head:                                     |                         |   |   |
| Consumit                   | nce of tank leakage from a s   |   | ent or numn tank held   | w the operating depth or e                    | ovidence of                             |
| damaged, cra               | nce of tank leakage from a s<br>cked, or structurally unsoun           | id maintenance hole cover                   | 's?                     | w the operating acpuiror o                    | .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |
| _                          | Tank   | Leaking Out                                 | Leaking In              | Cover Damage                                  |   |
|                            | Septic/Holding Tank #1   | ☐ Yes ☐ No                                  | Yes No                  | Tyes No                                       |   |
|                            | Septic/Holding Tank #2   | Yes No                                      | Yes No                  | ☐ Yes ☐ No                                    |   |
|                            | Pretreatment Tank  | ☐ Yes ☐ No                                  | ☐ Yes ☐ No              | ☐ Yes ☐ No                                    |   |
|                            | Pump Tank  | Yes No                                      | Yes No                  | ☐ Yes ☐ No                                    |   |
| 6. How many ga             | llons of septage were remo   | ved?  | ·                       |   |   |
| Tank #1 /600 Tank #2       |  | Pretreatment Tank Pr                        |                         | ump Tank                                      |   |
| 7. Other informa           | ation: List any troubleshoot   | ing, minor repairs conduc                   | ted, tank safety conce  | rns, or other concerns.                       |   |
|                            |  |   |                         |   |   |
| 8. Certification:          | I hereby certify as a State of and made the observations,              | or directly supervised other                | rs in the performance o | f this job.                                   |   |
| Maintainer's N             | Name: PINKY'S SEWER SERVIC   | E Maintainer's                              | Address: P.O. Box 354   | Afton, MN 55001                               |   |
| Maintainer's L             | icense #: 1673 Maint   | tainer's Phone #: 651-439-4                 | 1847                    |   |   |
| Maintainer's S             | Signature  | 1 Have                                      | Date: /                 | 0-30-15                                       |   |