

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply.	For local tracking purposes:
Submit completed form to Local Unit of Government (LUG) and system owner within 15 days	er
System Status	
System status on date (mm/dd/yyyy): 6/10/2020	
Reason(s) for noncompliance (check all applicable)	
☐ Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety	
☐ Other Compliance Conditions (Compliance Component #3) – Imminent	
☐ Tank Integrity (Compliance Component #2) — Failing to protect groundwater	
☐ Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater	
Soil Separation (Compliance Component #4) - Failing to protect groun	ndwater
☐ Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant	
Property Information Parcel ID# or Sec/Twp/l	Range: 01.026.21.11.0003
Property address: 11797 120 th Street S Reas	on for inspection: Sale of home
Property owner: Daniel King Owne	er's phone:612-384-1391
or	
Owner's representative:	
	latory authority phone:
Brief system description:	
Comments or recommendations:	
Certification	
I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.	
20 10 10 10 10 10 10 10 10 10 10 10 10 10	fication number: C9917
	icense number: 1106
	Phone number: 651-343-9117
Necessary or Locally Required Attachments	
Soil boring logs	per local ordinance
Other information (list):	