

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT



		Syster	n Location	
Address 11645	Pt Bouglas	D		Telephone Number
City Lostino	5	State M	1/ZIP 55033 Pro	operty ID No./GEO Code 36.027.21.
Owner )	Galla	Pumping C	Date 8/2/15	43.0010
- Justin		Cor	ntractor	
Maintainer MEYE	RSEWER	MPCA Licer	nse No. 915	Telephone Number 651-459-014
What was done to the system?			Report Liquid Capacity in Gallons	
Tank(s) Pumped			Tank 1: 1500	Pumped Tank 2: Pumped
Sludge and scum measured.			Tank 3:	Pumped Tank 4: Pumped
Do tanks need to be pumped?			Total Gallons Pun	
Yes No	(If no provide measuremen	nts below)		
Visual Inspection (	note any problems with	the system):	NOTE: This de	pes not serve as a compliance inspection
	*Tank Mea	surements-Use (	Only if Tank(s) Were NO	OT Pumped
Tank Length	in. <b>X</b> Tank Width	in. <b>X</b> Tar	nk Depth in. :	= Tank Volume (cubic inches)
Tank Radius	in. <b>X</b> Tank Radius	in. <b>X</b> 3.	.14 = Tank Volume (c	ubic inches)
Tank Volume (cu. in.)	/ 231.01 :	≠ Liquid Capaci	ty Gallons	/ Tank Depthin, = Gallons/Inch
Sludge Level	in. <b>X</b> Gallons Per Inch	= Slud	ge Volume Gal	lons
Scum Level	in. X Gallons Per Inch	= Scun	n Volume Ga	lons
Sludge Volume	+ Scum Volume	= Tota	I Sludge and Scum Volui	me Gallons
Total Sludge and Sci	um Volume	/ Liquid Capacit	y = Percer	nt Sludge and Scum in Tank %
Scum Layer Effluent			Tank Depth measured from invert of outlet	*Tanks must be pumped if either of the following conditions exist:  1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or  2. Total sludge and scum volume is greathan 25 percent of the tank's liquid