

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

| System Location | | | | | | | |
|--|--------------------|------------------|--|--------------|--|---|---|
| Address 1/09 | NORELL A | UE N | · · · · · · · · · · · · · · · · · · · | | Telephone N | umber | - |
| City Still Wat | ER- | | UZIP 550 | 292 Prop | erty ID No./GI | EO Code | |
| Owner BRUCE | Thordson | Pumping [| ~ / | 0/15 | , | | |
| | | Co | ntractor | | | | |
| Maintainer MEYER | SEWER | MPCA Licer | nse No. 9 | 15 | Telephone N | umber 65/- | 459-016 |
| What was done to the system? Report Liquid Capacity in Gallons | | | | | | \$ | |
| Tank(s) Pumped / | | | Tank 1: | 1200 | Pumped T | ank 2: | Pumped |
| Sludge and scum measured. Do tanks need to be pumped? | | | Tank 3: | |] Pumped _T | ank 4: | Pumped |
| Yes No (If no provide measurements below) | | | Total G | allons Pumpe | ed: 120 | 0 | |
| Visual Inspection (note | any problems with | the system): | нот | E: This does | not serve | as a complian | ce inspection. |
| | | | | | | | |
| | | | | | | | |
| | *Tank Meası | urements-Use (| Only If Tank(s |) Were NOT | Pumped | | |
| Tank Length in. | X Tank Width | in. X Tar | nk Depth | in. = | Tank Volume | (cubic inches) | |
| Tank Radius in. | X Tank Radius | in. X 3. | 14 = Tank | Volume (cubi | c inches) | | |
| Tank Volume (cu. in.) | / 231.01 = | Liquid Capacit | ty | Gallons / T | ank Depth | in. = Galloi | ns/Inch |
| Sludge Level in. | X Gallons Per Inch | = Sludg | ge Volume | Gallon | 5 | | |
| Scum Level in. | X Gallons Per Inch | = Scum | n Volume | Gallon | S . | | |
| Sludge Volume | + Scum Volume | = Total | Sludge and S | cum Volume | | Gallons | |
| Total Sludge and Scum Vo | olume / | Liquid Capacity | у | = Percent S | udge and Sci | um in Tank | % |
| Scum Layer Effluent Sludge Layer | | | Tank Depth n from invert o pipe to botto | foutlet | following co 1. The top of 12 inches fr baffle; or 2. Total slud | t be pumped if onditions exist: of the sludge lar om the botton dge and scum v cent of the tan | yer is less than n of the outlet rolume is greate |
| Signature 201 | | D | ate 9/3 | 0/15 | | Reset | Form |