DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance $12-9$	1-15 Reason for	Maintenance:	entire	-	
Property Address: 358	Wed A	Property	Owner's Name:	shn uzann	<u>. L</u>
Municipality:	<u>600</u> s	tate MN Zip Code _	GEO C	ode/Property I.D. #:	
What was done to th	e system?	Tank Measur	ements (must be co	ompleted if tanks NOT pump	ed)
Tank(s) Pumped		 Liquid Level of Tank	in. Sludge	Level in. Scum Level	j in.
Sludge and scum measure		-			
Do tanks need to be pump Yes No (If no pro	ear vide measur e ments)	Total (Sludge + Scum)	/ Liquid Le	evel = % Sludge & S	cum
1. Access used to remove sept		nce Hole	to #3 below)	* Tank must be pumped is greater than 25%.	if this value
2. If maintenance hole was use	ed, were all covers s	ecurely replaced?	es No please exp	plain	
Explanation: Manhole	on second t	ark nows to be	- respect		
3. If owner refuses to allow a them complete and sign th	Subsurface Sewag	je Treatment System (S		through the maintenance h	iole, have
l,	(owr	ner's name), refuse to allo	ow the removal of so	lids and liquids through the n	naintenance
hole. I understand that rem					
4. Is the tank designed as a lea	iky tank? <i>example:</i> so	eepage pit, cesspool, dryw	vell, leaching pit		
Tank#1 TYes To No J	erificatio Method U	sed:			•
Jahlahana Marana	/erificatio Method U			alougho appraise donth a	r ovidence o
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence o damaged, cracked, or structurally unsound maintenance hole covers?					
•	ank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1		TYes THO	TYes IL-No	Yes Mo	_
Septic/Holding Tank #2		Yes Wo	☐ Yes ☐ No	res No	_
Pretreatment Tank		☐ Yes ☐ No	☐ Yes ☐ No	Yes No	_
Pump Tank		Yes No	Yes No	☐ Yes ☐ No	_
6. How many gallons of sept	tage were removed	17			
Tank #1 /500 Ta	ink#2 /500	Pretreatment Tank	·	Pump Tank	
7. Other information: List ar	y troubleshooting	, minor repairs conduc	ted, tank safety co	ncerns, or other concerns.	
			<u> </u>		
8. Certification: I hereby cer and made t	tify as a State of Mir he observations, or	nnesota certified SSTS M directly supervised othe	aintainer that I perso rs in the performanc	nally conducted the work e of this job.	
Maintainer's Name: PINKY	'S SEWER SERVICE	Maintainer'	s Address: P.O. Box 3	854 Afton, MN 55001	
Maintainer's License #: 167	73 Maintair	er's Phone #: 651-439-	4847		
Maintainer's Signature Date: 12-9-15					