

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit m	ust be completed	
prior to perfor	ming maintenance activit	ties and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	5-24-16 Reason	for Maintenance:	<outine< td=""><td>= Maint</td><td>enance</td></outine<>	= Maint	enance	
Property Address:	510 Neal Av	e N P	roperty Owner's N	ame: David	Latorle	
1	water ZIP:550					
Maintenance Permit N	·9575 y 1507	Maintainer Name an	d License No. Ron	s sewer service/ Lz ic		
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
	no provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers se 3. Is there evidence	nove septage: A Maintena curely replaced? A Yes of tank leakage from a se aged, cracked, or structu	□ No ptic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
evidence of dam.	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes TNo	☐ Yes PNo		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were remove	d?				
Tank #1 /500 gal Tank #2 gal Pretreatment tank gal Pump Tank					gal	
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.	
	97					