## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	nce //-18-15 Reason for	Maintenance:	tori		
Property Address	15399 95 tyl. L	)- Property	Owner's Name: Picha	rd MaDonong 4.	
Municipality:	tillant	State MD Zip Code	<del></del>		<u> </u>
What wa	as done to the system?	Tank Measu	rements (must be comp	oleted if tanks NOT pumpe	d)
<ul> <li>Tank(s) Pumped</li> <li>Sludge and scum measured.</li> <li>Do tanks need to be pumped?</li> <li>Yes □ No (If no provide measurements)</li> </ul>		Liquid Level of Tank	in. Sludge Lev	vel in. Scum Level	in.
		-		*	
		Total (Sludge + Scum) / Liquid L	Liquid Level		
	remove septage: Maintena		to #3 below)	* Tank must be pumped if is greater than 25%.	this value
2. If maintenance	hole was used, were all covers :	securely replaced?	es 🔲 No <b>please explai</b>		
Explanation:		(			
3. If owner refus	es to allow a Subsurface Sewa e and sign the following state		SSTS) to be pumped th	rough the maintenance ho	le, have
l,	(ow	ner's name), refuse to allo	ow the removal of solids	and liquids through the ma	intenance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank desi	igned as a leaky tank? example: :	seepage pit, cesspool, dryw	vell, leaching pit		
Tank#1 Yes No Verificatio Method Used:					
Tank#2 TV	as TiNo Verificatio Method	lsed:			
Tank#2 Yes No Verificatio Method Used:  5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of					
damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes X No	Yes No	
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	
	Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
	Pump Tank	Yes No	Yes No	Yes No	
6. How many ga	llons of septage were remove	d?			
Tank #1 150	Tank #2	Pretreatment Tank F		Pump Tank	
7. Other inform	ation: List any troubleshootin	g, minor repairs conduc	ted, tank safety conce	rns, or other concerns.	
8. Certification:	I hereby certify as a State of Mi and made the observations, or	directly supervised othe	rs in the performance of	this job.	
Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 354 Afton, MN 55001					
Maintainer's L	icense #: 1673 Maintai	ner's Phone #: 651-439-	4847		
Maintainer's S	ignature	<b>\</b>	Date: ₫	1-18-15	