DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT			
Date of Maintenance / 2 / Beason for Maintenance: 6 / Go /			
Property Address: 9646 Stoucher Ago Property Owner's Name: Frank Pumpt			
Municipality: State MZip Code GEO Code/Property I.D. #:			
What was done to the system?	Tank Measure	ments (must be comp	leted if tanks NOT pumped)
Tank(s) Pumped Sludge and scum measured.	Liquid Level of Tank	in. Sludge Leve	el in. Scum Level in.
Do tanks need to be pumped? Yes No (If no provide measurements)	Total (Sludge + Scum)	/ Liquid Level	= % Sludge & Scum
1. Access used to remove septage: Maintenance Hole (Go to #3 below) * Tank must be pumped if this value is greater than 35%			
is greater than 25%. 2. If maintenance hole was used, were all covers securely replaced? Yes No please explain			
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:			
Septic/Holding Tank #1	Yes TNo	Yes No	T Yes TAIO
Septic/Holding Tank #2	☐ Yes ☐ No	Yes ZNo	Yes CNO
Pretreatment Tank	┌ Yes ┌ No	☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
6. How many gallons of septage were removed? Tank #1			
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintainer's Name: SMILIE'S SEWER SERVICE Maintainer's Address: Scandia, MN			
Maintainer's License #: 2428 Maintainer's Phone #: 651-433-3005 Maintainer's Signature Date: 12245			