DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

| SST | S MAINTEN | NCE REPORT | | |
|--|---|-----------------------------|--|----------|
| Date of Maintenance | Maintenance: | en Mari | | |
| Property Address: 12563 624 | 1 ST Vroper | ty Owner's Name: | nde Armstron | - 4 |
| Municipality: 5/1/water St | tate ///Zip Code | 5508 GEO Cod | e/Property I.D. #: | <u>/</u> |
| What was done to the system? | Tank Measurements (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped Sludge and scum measured. | Liquid Level of Tank in. Sludge Level in. Scum Level in. | | | |
| Do tanks need to be pumped? Tyes No (If no provide measurements) | Total (Sludge + Scu | m)/ Liquid Leve | = % Sludge & Scum | * |
| 1. Access used to remove septage: Maintenan | ce Hole \(\int \) Other (G | io to #3 below) | * Tank must be pumped if this value is greater than 25%. | ; |
| 2. If maintenance hole was used, were all covers se | curely replaced? | es No please expla | | |
| Explanation: | | | | |
| 3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem | _ | (SSTS) to be pumped th | rough the maintenance hole, have | • |
| l, (own | er's name), refuse to a | allow the removal of solids | s and liquids through the maintenance | <u>.</u> |
| hole. I understand that removal of solids and liq | | | | |
| 4. Is the tank designed as a leaký tank? example: se | epage pit, cesspool, dr | ywell, leaching pit | | |
| Tank#1 Tyes TNo Verificatio Method Us | sed: () | 0 (00 | | |
| Tank#2 Yes No Verificatio Method Us | / | | - | _ |
| 5. Is there evidence of tank leakage from a sept damaged, cracked, or structurally unsound m | | | w the operating depth or evidence | _ of |
| Tank | Leaking Out | Leaking In | Cover Damage | |
| Septic/Holding Tank #1 | Yes No | Yes Civo | T Yes No | |
| Septic/Holding Tank #2 | ☐ Yes ☐ No | / Yes No | ☐ Yes ☐ No | |
| Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | Yes No | |
| 6. How many gallons of septage were removed: | ? | | | |
| Tank #1 /5/00 Tank #2 | Pretreatment Tank | | mp Tank | |
| 7. Other information: List any troubleshooting, | minor repairs cond | ucted, tank safety conce | rns, or other concerns. | |
| · · · | - | · | | |
| 8. Certification: I hereby certify as a State of Mini and made the observations, or d | | | | _ |
| Maintainer's Name: SMILIE'S SEWER SERVICE | Maintaine ——— | er's Address: Scandia, MN | | |
| Maintainer's License #: 2428 Maintaine | er's Phone #; 651-43: | 3-3005 | | |
| Maintainer's Signature | 12/ | Date: | ->9-16 | |