H has C has I V has had

JAN 05 2016

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

PUBL	O HADANTH SS	TS MAINTENA	NCE REPORT	1	,
Date of Maintenance	Reason fo	or Maintenance:	on Main	<i>t</i>	
Property Address: /	03/0 Kisin	of Ly Propert	y Owner's Name:	ary Opel	
Municipality:	Munter	State ////Zip Code_	55 (R) GEO Cod	e/Property I.D. #:	
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank	Liquid Level of Tank in. Sludge Level in. Scum Leve		in.
Sludge and scum measured.		Liquid Ecver of Tarik	III Sladge Le		
Do tanks need to be pumped? Yes No (If no provide measurements)		Total (Sludge + Scun	n) / Liquid Leve	= % Sludge & Scun	n
			o to ## bolow)	* Tank must be pumped if t	his value
	ove septage: Mainten	j,		is greater than 25%.	
2. If maintenance hold	was used, were all covers	securely replaced?	Yes ∣No piease expia	in	
Explanation:				<u> </u>	. <u>-</u> -
	allow a Subsurface Sewa d sign the following state		(SSTS) to be pumped th	rough the maintenance hole	e, have
	{ov	vner's name), refuse to a	llow the removal of solids	s and liquids through the mair	ntenance
hole. Lunderstand	that removal of solids and				
4. Is the tank designed	d as a leaky tank? example:	seepage pit, cesspool, dry	well, leaching pit		
Tank#1 Yes	No Verificatio Method	Used:	> Cas	> /	
Tank#2 Yes	No Verificatio Method	Used:			
5. is there evidence	of tank leakage from a se	ptic, holding, pretreati	ment or pump tank belo	w the operating depth or ev	idence of
damaged, cracked	l, or structurally unsound		1		
	Tank	Leaking Out	Leaking In	Cover Damage	
	ptic/Holding Tank #1	T Yes No	Yes 7 No	Yes TCM6	
Se	ptic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
Pre	etreatment Tank	Yes No	Yes No	Yes No	
Pu	mp Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
6. How many gallon	s of septage were remove	ed?			
Tank #1 / 00	Tank #2	Pretreatment Tai	nk Pu	mp Tank	
7. Other information	n: List any troubleshootir	ng, minor repairs condu	icted, tank safety conce	rns, or other concerns.	
				<u> </u>	
8. Certification: The	ereby certify as a State of N d made the observations, o	linnesota certified SSTS I or directly supervised oth	Maintainer that I personal ers in the performance o	lly conducted the work f this job.	
Maintainer's Name	:: SMILIE'S SEWER SERVICE	Maintaine	r's Address: Scandia, MN		
Maintainer's Licen		· 1 Di . # 651 473	2225		
	se #: 2448 Mainta	iner's Phone #: 651-433	======================================	110-16	