RECENTED

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

JAN 05 2016

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730 SSTS MAINTENANCE REPORT

Date of Maintenance WEZA B	eason for M	Naintenance:	of Ma	5	
Property Address: 20360	En	eld CPrope	rty Owner's Name:	m Marguara	
Municipality: Ores	Sta	ate ////Zip Code	550ZGEO Code	e/Property I.D. #:	
What was done to the system? Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped?		Tank Measurements (must be completed if tanks NOT pumped)			
		Liquid Level of Tan		*	
Yes No (If no provide meas	urements)	Total (Sludge + Scu	im) / Liquid Level	= % Sludge & Scum	
1. Access used to remove septage: Maintenance Hole Cother (Go to #3 below) * Tank must be pumped if this value is greater than 25%.					
2. If maintenance hole was used, were al	l covers sec	urely replaced?	Yes No please explain		
Explanation:					
3. If owner refuses to allow a Subsurfa them complete and sign the followi			n (SSTS) to be pumped thr	ough the maintenance hole, have	
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of sol	ids and liqu	ilds through other a	ccess points is not consider	ed maintenance.	
4. Is the tank designed as a leaky tank?	xample: see	page pit, cesspool, di	rywell, leaching pi	1	
Tank#1 Yes No Verificatio	Method Use	ed: Dec	- 665		
Tank#2 Yes No Verificatio	Method Use	ed:			
5. Is there evidence of tank leakage from damaged, cracked, or structurally u	_			v the operating depth or evidence of	
Tank		Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank	‡ 1 [Yes No	☐ Yes ☐ No	Yes Ao	
Septic/Holding Tank	‡2 [Yes No	☐ Yes ☐ No	Yes No	
Pretreatment Tank	. Г	Yes No	☐ Yes ☐ No	Yes No	
Pump Tank	. [Yes Xo	Yes No	☐ Yes ☐ No	
6. How many gallons of septage were	removed?				
Tank #1 Tank #2		Pretreatment Tank Pum		np Tank	
7. Other information: List any trouble	shooting, r	ninor repairs cond	ucted, tank safety concer	ns, or other concerns.	
				No.	
8. Certification: I hereby certify as a Strand made the observa			Maintainer that I personally hers in the performance of t	•	
Maintainer's Name: SMILIE'S SEWER	SERVICE	Maintain	er's Address: Scandia, MN		
Maintainer's License #: 2428	Maintainer	's Phone #: 651-43			
Maintainer's Signature	añ	110	Men Date: //	-2545	