

OSTP Soil Observation Log



Project ID: v 03.19.15

Client/ Address:		13186 24th Street Court N		Legal Description/ GPS:		20.029.20.31.0006	
Soil parent material(s): (Check all that apply)							
<input checked="" type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Loess		<input type="checkbox"/> Till	
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input checked="" type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Foot Slope	
<input type="checkbox"/> Toe Slope		<input type="checkbox"/> Toe Slope		<input type="checkbox"/> Bedrock		<input type="checkbox"/> Organic Matter	
Landscape Position: (check one)		Soil survey map units		Slope %		Elevation:	
0-18"		Fine Sandy Loam		6.0		09/30/20	
18 - 30"		Sandy Loam		6.0		09/30/20	
30" - 50"		Loamy Sand		6.0		09/30/20	
Weather Conditions/Time of Day:		noon - sunny		Date		09/30/20	
Observation #/Location:		Marked on map		Observation Type:		Auger	
Depth (in)		Texture		Rock Frag. %		Matrix Color(s)	
0-18"		Fine Sandy Loam		<35%		7.5YR 5/3	
18 - 30"		Sandy Loam		<35%		7.5YR 5/4	
30" - 50"		Loamy Sand		<35%		7.5YR 5/3	
Redox Kind(s)		Mottle Color(s)		Indicator(s)		Shape	
Granular		Granular		Granular		Granular	
Blocky		Blocky		Blocky		Blocky	
Structure		Grade		Consistence			
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schломка		1106		9/30/2020			
(Designer/Inspector)		(Signature)		(License #)		(Date)	