Prop	perty	address: 13186 24th Street Court	N.	Inspector initials/Date: ss 09/30/2020		
					(mm/dd/yyyy)	
4	1	mant on Dublic Haalth C			114 - F F	
<u> </u>	IIII	pact on Public Health – C	omplian	ce compor	nent #1 of 5	
	Co	Compliance criteria:			Verification method(s):	
	Sv	stem discharges sewage to the	☐ Yes ⊠ No		Searched for surface outlet ■	
	ground surface.				Searched for seeping in yard/backup in home	
	System discharges sewage to drain tile or surface waters.		☐ Yes	⊠ No	Excessive ponding in soil system/D-boxes	
			L res Mino			
	System causes sewage backup into dwelling or establishment.		ПУес	⊠ No	Homeowner testimony (See Comments/Explanation)	
			☐ Yes ⊠ No		 □ "Black soil" above soil dispersal system □ System requires "emergency" pumping □ Performed dye test □ Unable to verify (See Comments/Explanation) 	
				W_W		
		Any "yes" answer above indicates the system is an imminent threat to public health and safety.				
5	116				☐ Other methods not listed (See Comments/Explanation)	
	Co	Comments/Explanation:				
-						
<u>Z.</u>	Ia	Tank Integrity — Compliance component #2 of 5				
у.	Compliance criteria:				Verification method(s):	
æ	Svs	stem consists of a seepage pit, spool, drywell, or leaching pit.	ПYes	⊠ No	☐ Probed tank(s) bottom	
			100		Examined construction records	
	Sec	epage pits meeting 7080.2550 may be				
	con	compliant if allowed in local ordinance.			Examined Tank Integrity Form (Attach)	
	Ser	wage tank(s) leak below their	☐ Yes	⊠ No	Observed liquid level below operating depth	
		designed operating depth.		23 140	☐ Examined empty (pumped) tanks(s)	
		es, which sewage tank(s) leaks:			☐ Probed outside tank(s) for "black soil"	
	Any "yes" answer above indicates the				☐ Unable to verify (See Comments/Explanation)	
		(5)			Other methods not listed (See Comments/Explanation)	
	system is failing to protect groundwater.			iter.		
	Comments/Explanation: Maintainer pumped and examined the day before the inspection. See attached tank report.					
					on. See attached tank report.	
3.	3. Other Compliance Conditions – Compliance component #3 of 5				ponent #3 of 5	
	 a. Maintenance hole covers are damaged, cracked, unsecured, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unknot b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. ☐ Yes* ☒ No ☐ Unknot 					
*System is an imminent threat to public health and safety.				ety.		
		Explain:				
	C.	. System is non-protective of ground water for other conditions as determined by inspector . ☐ Yes* ☒ No				
*System is failing to protect groundwater.				and an animal by morpholor.		
	Explain:					

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31b • 6/4/14 Page 2 of 3