## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenan	ice 11-10-15 Reason for	Maintenance:	20utne		
Property Address:	14480 594C	Propert	y Owner's Name: <u></u> <u></u>	on Heyman	
Municipality:	AFton !	State MM Zip Code	GEO Cod	e/Property I.D. #:	
What wa	sidone to the system?	Tank Meas	urements (must be com	pleted if tanks NOT pumped).	
Tank(s) Pumped  Sludge and scum measured.  Do tanks need to be pumped?		Liquid Level of Tank  Total (Sludge + Scur		<u> </u>	in. — *
1. Access used to r	No ( <i>If no provide measurements</i> remove septage: <b>Z</b> Maintena	nce Hole		* Tank must be pumped if thi is greater than 25%.	s value
Explanation:	hole was used, were all covers s				have
3. If owner refuse them complete	s to allow a Subsurface Sewa and sign the following state	ge i reatment system ment:	(3513) to be pumped ti	nrough the maintenance hole,	IIUVC
Tank#1 Yes  Tank#2 Yes  5. Is there eviden	and that removal of solids and ligned as a leaky tank? example: s  No Verificatio Method lights in the lights of tank leakage from a segment of tank leakage from a segment of tank  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	quids through other actepage pit, cesspool, dry  Jsed:  Jsed:  ptic, holding, pretreat maintenance hole cov  Leaking Out  Yes No	ment or pump tank belovers?  Leaking In  Yes No	Cover Damage Yes No	
	Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
Tank #1 / 50	Pump Tank  lons of septage were remove  Tank #2  tion: List any troubleshootin	d?  Pretreatment Ta	nk Pi	ump Tank	
	I hereby certify as a State of Mi and made the observations, or ame: PINKY'S SEWER SERVICE cense #: 1673 Maintai	directly supervised oth	ners in the performance of P.O. Box 354	f this job. 4 Afton, MN 55001	