

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a vali	d maintenance pe	rmit. This permit mu	ist be completed
Inis section must be	ming maintenance activition	os and romain on-	site for the duration	on of the maintenanc	e activity.
<u>prior</u> to perfori				of the manifestance	,
Date of Maintenance:	5/23/16 Reason f	for Maintenance: _	KOUPI.	20	
Property Address: 8490 Janiaca Avel Property Owner's Name: Jen Cleaning					
Municipality; 5/1/	Water ZIP:		tification Number:		-2428
Maintenance Permit No	0:96321p/408M	aintainer Name an	d License No. Sy	ilies Sewer	Service
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 2. Were all covers securely replaced? Yes No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 1005 gal Tank #2 1000 gal Pretreatment tank 1000 gal Pump Tank gal					
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.
-					
	19				