

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance per	mit. This permit m	ust be completed
prior to perfor	ming maintenance activiti	es and remain on-	site for the duratio	n of the maintenan	ce activity.
Date of Maintenance:	5-23-/6 Reason f	for Maintenance: _	Cleaning		
Property Address: 13820 116th St N Property Owner's Name: Alice Falconer					alconer
Municipality: Still	mater ZIP: 550;	82 Property Ider	itification Number:		
	D: 1299621419 M				r 2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes 🗌 No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec3. Is there evidence of	nove septage: Maintenan curely replaced? Yes of f tank leakage from a sept ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump t	ank below the oper	ating depth or
20	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ੴNo	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
,	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?)			
Tank #1 1,500 gal Tank #2		gal Pretreatmen	t tankga	l Pump Tank	gal gal
	: List any troubleshooting,	minor repairs co	nducted, tank safet	y concerns, or othe	er concerns.