DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance //-25-/5 Reason for M	Maintenance: 💎	utra		
Property Address: 1337 134 St N	_	Owner's Name:	en trout	<u>e</u>
Municipality: LCXL Elmo Sta	ate Mn Zip Code	GEO Code	Property I.D. #:	
What was done to the system?	Tank Measur	ements (must be comp	eted if tanks NOT pumpe	d)
☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped?	Liquid Level of Tank Total (Sludge + Scum)	in. Sludge Lev	in. Scum Level = % Sludge & Scu	in. * m*
Yes No (If no provide measurements) 1. Access used to remove septage:		to #3 below)	* Tank must be pumped if is greater than 25%.	this value
2. If maintenance hole was used, were all covers see Explanation:	curely replaced?	es No please explair		
3. If owner refuses to allow a Subsurface Sewage them complete and sign the following statem	e Treatment System (S ent:	SSTS) to be pumped thr	ough the maintenance ho	le, have
I, (owner hole. I understand that removal of solids and liques. Is the tank designed as a leaky tank? example: see Tank#1 Yes Yes No Verificatio Method Us	uids through other acco	ess points is not consider	and liquids through the ma ed maintenance.	intenance
5. Is there evidence of tank leakage from a sept damaged, cracked, or structurally unsound m	ic, holding, pretreatm	ent or pump tank belov	v the operating depth or e	evidence o
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes LNo	Yes PNo	Yes K	
Septic/Holding Tank #2	Yes KNo	Yes No	T Yes T No	
Pretreatment Tank	Yes No	TYes TNo	☐ Yes ☐ No	
Pump Tank	Yes No	Yes No	Yes No	•
Pump Tank 6. How many gallons of septage were removed	England Special	Yes No	Yes No	•
	England Special	Tanana Tanana	Yes No	,
6. How many gallons of septage were removed	? Pretreatment Tan	k Pur	np Tank	
6. How many gallons of septage were removed Tank #1 1000 Tank #2 500	Pretreatment Tank, minor repairs conductions of the conduction of	k Purcted, tank safety concer	np Tank ns, or other concerns. y conducted the work this job.	