



Client/ Address:		2327 Morgan Ave N		Legal Description/ GPS:		190290420014	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Toe Slope	
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Loess		<input type="checkbox"/> Till	
<input type="checkbox"/> Alluvium		<input type="checkbox"/> Bedrock		<input type="checkbox"/> Organic Matter			
Landscape Position: (check one)							
<input type="checkbox"/> Lawn		<input type="checkbox"/> Soil survey map units		<input type="checkbox"/> Slope %		<input type="checkbox"/> Elevation:	
Weather Conditions/Time of Day:		Sunny 3:30		Date		12/04/00	
Observation #/Location:		2' outside line 1 in STA		Observation Type:		Auger	
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Consistence
0-6"	Loam	<35%					
6-30"	Loamy Sand	<35%	7.5YR 5/6				
30-60"	Coarse Sand	<35%	5YR 4/6				
60-72"	Sand	<35%	10YR 5/4				
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schlomka		L4137		12/8/2020			
(Designer/Inspector)		(Signature)		(License #)		(Date)	