

OSTP Soil Observation Log

Project ID: v 03.19.15



Client/ Address:		7680 Lamar Ave S		Legal Description/ GPS:		12/2/2020	
Soil parent material(s): (Check all that apply)				Organic Matter			
<input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope				<input type="checkbox"/> Bedrock <input type="checkbox"/> Alluvium			
Landscape Position: (check one)		Soil survey map units		Slope shape		Elevation:	
Lawn						12/02/20	
Weather Conditions/Time of Day:				Date			
SUN NOON				12/02/20			
Observation #/Location:				Observation Type:			
2' outside STA				Auger			
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Consistence
0-6"	Loamy Sand	<35%	7.5YR 2.5/3				
6" - 40"	Sand	<35%	7.5YR 4/6				
40" - 72"	Coarse Sand	<35%	10YR 4/6				
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schlomka				L4137		12/2/2020	
(Designer/Inspector)				(License #)		(Date)	