DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintena	nce 12-11-15 Reason	for Maintenance: V	itine		<u> </u>
Property Address	= 7980 Demontre	Ulla TVI N Proper	ty Owner's Name:	a skarda	Jr.
Municipality: <u>(</u>	ike Elmo	State <u>Mu</u> Zip Code	55042 GEO COO	le/Property I.D. #:	
Whatwa	as done to the system?	Tank Meas	urements (must be com	pleted if tanks NOT pump	ed)
Tank(s) Pump	ed	 Liquid Level of Tank	in. Sludge Le	evel in. Scum Level	in.
!	tum measured.				*
l <u> </u>	d to be pumped? No (<i>If no provide measuremer</i>	Total (Sludge + Scur	n)/ Liquid Leve	el = % Sludge & So 	
* Tank must be pumped if this value is greater than 25%.					
2. If maintenance	hole was used, were all cover	s securely replaced? 🛛 📜	¥es ☐ No please expla	in	
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of					
damaged, cra	cked, or structurally unsoun Tank	d maintenance noie cov Leaking Out	ers: Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes SN6	Yes T-No	☐ Yes ☐ No	-
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	-
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	-
	Pump Tank	☐ Yes ☐ No	Yes No	Yes No	_
6. How many gallons of septage were removed?					
Tank #1 /500 Tank #2 Pretreatment Tank Pump Tank					
7. Other informa	ation: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conce	erns, or other concerns.	
8. Certification:	I hereby certify as a State of I and made the observations,	or directly supervised oth	ers in the performance o	of this job.	
Maintainer's N	iame: PINKY'S SEWER SERVIC	E Maintaine	er's Address: P.O. Box 354	Afton, MN 55001	
Maintainer's L	icense #: 1673 Maint	ainer's Phone #: 651-439	9-4847 		
Maintainer's S	ignature him	A Clima	Date: 🖊	2-11-15	