## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT				
Date of Maintenance Reason for I	Maintenance:	o Main		
Property Address: 23700 Marc	Propert	Owner's Name:	ay Schleo	7 <u>/</u> e
Municipality: Scandya St	ate ZZip Code_	SGEO Cod	e/Property I.D. #:	<i></i>
What was done to the system?	Tank Meası	Tank Measurements (must be completed if tanks NOT pumped)		
<ul><li>✓ Tank(s) Pumped</li><li>☐ Sludge and scum measured.</li></ul>	Liquid Level of Tank in. Sludge Level in. Scum Level in.			
Do tanks need to be pumped?  Yes No (If no provide measurements)	Total (Sludge + Scun	n)/ Liquid Leve	= % Sludge & Scum	<del>*</del>
1. Access used to remove septage: Maintenan	ce Hole Cother (Go	to#3 below)	* Tank must be pumped if this vis greater than 25%.	value
2. If maintenance hole was used, were all covers see	curely replaced?	Yes TiNo please expla	in	
Explanation:				
3. If owner refuses to allow a Subsurface Sewage them complete and sign the following statem		(SSTS) to be pumped th	rough the maintenance hole, ha	ave
l, (owne	er's name), refuse to al	low the removal of solids	and liquids through the mainten	nance
hole. I understand that removal of solids and liqu			•	
4. Is the tank designed as a leaky tank? example: see	epage pit, cesspool, dry	well, leaching pit	1	
Tank#1 Yes No Verificatio Method Us	ed:			
Tank#2 Tes Tho Verificatio Method Us	ed: T			
5. Is there evidence of tank leakage from a septi damaged, cracked, or structurally unsound m			w the operating depth or evide	nce of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes ☐ N6	Yes Liko	
Septic/Holding Tank #2	Yes I No	☐ Yes 🚺 No	Yes No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
6. How many gallons of septage were removed?				
Tank #1 / Tank #2 / Tank #2	Pretreatment Tan	k Pui	mp Tank 	
7. Other information: List any troubleshooting,	minor repairs condu	cted, tank safety conce	ns, or other concerns.	
8. Certification: I hereby certify as a State of Minr and made the observations, or d				
Maintainer's Name: SMILIE'S SEWER SERVICE	Maintainer	's Address: Scandia, MN		
Maintainer's License #: 2428 Maintaine	r's Phone #; 651-433	-3005	>-/2/5	
	111	~ ~ · · · /	, , , , , , , , , , , , , , , , , , ,	