## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSIS MAINTENANCE REPORT			
Date of Maintenance 1221-15 Reason for Maintenance: Log Maintenance			
Property Address: 14911 225rd Property Owner's Name: Hos Syoun			
Municipality: Scaudia State // Zip Code SEO Code/Property I.D. #:			
What was done to the system?	Tank Measurements (	(must be completed if ta	inks NOT pumped)
Tank(s) Pumped Sludge and scum measured.	Liquid Level of Tank	in. Sludge Level i	in. Scum Level in.
Do tanks need to be pumped?  Yes No (If no provide measurements)	Total (Sludge + Scum)	/ Liquid Level ===================================	* % Sludge & Scum
1. Access used to remove septage: Maintenance Hole			
is greater than 25%.  2. If maintenance hole was used, were all covers securely replaced?  Yes No please explain			
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:			
I, (own	er's name), refuse to allow the rei	moval of solids and liquid	s through the maintenance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1   Yes   No Verificatio Method Used:			
Tank#2 Yes No Verificatio Method Used:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?			
Tank	ĺ	ring In Cover I	Damage
Septic/Holding Tank #1	Yes XVO Yes	No T Yes	IZNO
Septic/Holding Tank #2	T Yes No Yes	□No □ Yes	;
Pretreatment Tank	TYes No TYes	□ No □ □ Yes	: Г.No
Pump Tank	Yes Yes	Yes Yes	7 No
6. How many gallons of septage were removed?			
Tank #1 / ( Tank #2	Pretreatment Tank	Pump Tank	500
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.			
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.			
Maintainer's Name: SMILIE'S SEWER SERVICE Maintainer's Address: Scandia, MN			
Maintainer's License #: 428 Maintainer's Phone #: 651-433-3005			
Maintainer's Signature		Date:	1-//