DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

12 10 15	'S MAINTENA	NCE REPORT	1
Date of Maintenance / 270 Reason for	Maintenance:	> //ain	
Property Address: 250 Old Wild	Waid Repropert	y Owner's Name: B_{r}	ran HamernoEl
Municipality: /antomede St	ate ////Zip Code_		e/Property I.D. #:
What was done to the system?	Tank Measi	rements (must be com	pleted if tanks NOT pumped)
Tank(s) Pumped	11		in Countries in
Sludge and scum measured.	Liquid Level of Tank	in. Sludge Le	vel in. Scum Level in.
Do tanks need to be pumped?	Total (Sludge + Scun	n) / Liquid Leve	.l = % Sludge & Scum
Yes No (If no provide measurements)	Total (Sladge 1 Seal)		
1. Access used to remove septage: Maintenan			 * Tank must be pumped if this value is greater than 25%.
2. If maintenance hole was used, were all covers se	curely replaced?	🌿 🦳 No please expla	in
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:			
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 Yes No Verificatio Method Used:			
Tank#2 Yes Verificatio Method Us	ed:		
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?			
Tank	Leaking Out	Leaking	Cover Damage
Septic/Holding Tank #1	Yes / No	Yes No	Yes No
Septic/Holding Tank #2	Yes 7 No	T Yes CNO	Yes 7 No
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	Yes No	Yes No	Yes No
6. How many gallons of septage were removed		······································	
Tank #1 / Tank #2 / Pretreatment Tank Pump Tank			
7. Other information: List any troubleshooting,	minor renairs condu	cted tank safety conce	rns or other concerns
7. Other information. List any troubleshooting,	mmor repairs condu	cted, talk salety colice	ma, or other concerns.
8. Certification: I hereby certify as a State of Minr and made the observations, or d			
Maintainer's Name: SMILIE'S SEWER SERVICE Maintainer's Address: Scandia, MN			
Maintainer's Name: SMILLE S SEWER SERVICE	Maintainer	's Address: Scandia, MN	
·	Maintainer		> 10 15